



April 22, 2011

MR. JOHN GIBBONS SENIOR MANAGER TECHNICAL COMPLIANCE NISSAN NORTH AMERICA, INC. P.O BOX 685001 FRANKLIN TN 37068-5009 NVS-215dgl 11V-244

SUBJECT: FRAME/BODY STRUCTURE CORROSION

DEAR MR. GIBBONS:

This letter serves to acknowledge Nissan North America Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a defect in the vehicles listed below for which a safety recall campaign will be conducted pursuant to Federal law.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

NISSAN/PATHFINDER/1996-2004 INFINITI/QX4/1997-2003

NHTSA Campaign Number: 11V-244

Mfg's Report Date: April 20, 2011

Components: STEERING: COLUMN

SUSPENSION: FRONT

Potential Number of Units Affected: 195,991

Summary:

NISSAN IS RECALLING CERTAIN MODEL YEAR 1996-2004 PATHFINDER AND MODEL YEAR 1997-2003 INFINITY QX4 VEHICLES ORIGINALLY SOLD, OR CURRENTLY REGISTERED IN THE DISTRICT OF COLUMBIA, CONNECTICUT, DELAWARE, IOWA, ILLINOIS, INDIANA, MASSACHUSETTS, MAINE, MARYLAND, MICHIGAN, MINNESOTA, MISSOURI, NEW HAMPSHIRE, NEW JERSEY, NEW YORK, OHIO, PENNSYLVANIA, RHODE ISLAND, VERMONT, WASHINGTON D.C., WEST VIRGINIA AND WISCONSIN. IN AREAS OF THE COUNTRY IN WHICH HEAVY CONCENTRATIONS OF ROAD SALT ARE USED, A MIXTURE OF SNOW/WATER AND SALT MAY ENTER AN ASSEMBLY LOCATION HOLE IN THE UPPER STRUT HOUSING, CAUSING WATER TO COLLECT AT THE MATING SURFACE OF THE STRUT HOUSING PANEL AND THE INNER HOOD LEDGE ASSEMBLY. OVER TIME, THIS SNOW/WATER AND SALT INTRUSION MAY RESULT IN CORROSION OF THE STRUT TOWER HOUSING IN SOME SUBJECT VEHICLES.

Consequence:

THE STRUT HOUSING MAY CRACK AND PULL AWAY FROM THE INNER HOOD LEDGE ASSEMBLY. THIS MAY LEAD TO GRINDING NOISES, INCREASED STEERING EFFORT, AND POSSIBLY THE STEERING COLUMN TO BREAK, RESULTING IN THE LOSS OF STEERING CONTROL, WHICH COULD RESULT IN A CRASH.

Remedy:

NISSAN WILL INSPECT THE STRUT HOUSING AND REPAIR THE VEHICLES AS NECESSARY FREE OF CHARGE. AN INTERIM NOTIFICATION LETTER TO OWNERS WILL BE MAILED ON OR BEFORE MAY 16, 2011. OWNERS MAY CONTACT NISSAN AT 1-800-647-7261.

Notes:

CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO HTTP://WWW.SAFERCAR.GOV.

This recall was the subject of a Preliminary Evaluation, PE11-004, conducted by the Office of Defects Investigation.

Please provide the following additional information and be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within 30 days after the close of the calendar quarter in which the campaign was initiated. Thereafter, quarterly reports will be due on or before 30 days after close of the calendar quarter.

Your contact for this recall will be Delia Lopez who may be reached by phone at 1-202-366-9525, or by email at Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you toward a successful completion of this recall campaign.

Sincerely,

Jennifer Timian

Chief, Recall Management Division

Office of Defects Investigation

Enforcement